





Project Operations

Oroville storage running below average for this time of year, Due to dry winter. Delta exports increased starting July 1, with X2 and OMR standards dropping off. Exports for the remainder of the summer controlled by upstream reservoir supply availability, with outflow as required to meet salinity standards. SWP exports have been low due to limited Oroville storage availability. CVP has continued to use Joint Point pumping at Banks Pumping Plant.



